

MULTI-POINT INSPECTION REPORT

Reset



Gregorie Gouth

2004 Porsche Carrera 4S 3.8

CUSTOMER NAME

YEAR / MODEL

ENGINE SIZE

CKU3696

75794

WPOAA29974S622295

07/05/26

HO / TAG

MILEAGE

VIN

DATE

Checked and Okay at this time

May Require Future Attention

Requires Immediate Attention

Check Fluid Levels and Fill

OK FILL

OK FILL

- ☒ ☐ Engine Oil
- ☒ ☐ Windshield Washing
- ☒ ☐ Power Steering
- ☐ ☐ Transmission (if equipped w/ dipstick)
- ☒ ☐ Brake Reservoir
- ☐ ☐ Headlamp Washer
- ☒ ☐ Coolant Recovery Reservoir

Check Following Systems / Components

- ☒ ☐ Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps
- ☒ ☐ Visually inspect headlamp alignment
- ☒ ☐ Windshield washer spray, wiper operation and wiper blades
- ☒ ☐ Windshield cracks and/or chips
- ☒ ☐ Heating, ventilation and air conditioning check
- ☒ ☐ Engine air cleaner filter
- ☒ ☐ Oil and/or fluid leaks
- ☒ ☐ Constant velocity (CVI drive axle boots if equipped)
- ☒ ☐ Exhaust system (leaks, damage, loose parts)
- ☒ ☐ Steering and steering linkages
- ☒ ☐ Stocks/struts, air suspension and other suspension components for leaks and/or damage
- ☒ ☐ Brake systems (including lines, hoses and parking brake)
- ☒ ☐ Engine cooling system, hoses and clamps
- ☒ ☐ Radiator, heater and air conditioning hoses for leaks / damage
- ☒ ☐ Accessory drive belts
- ☒ ☐ Clutch operation (if equipped)
- ☐ ☐ State inspection due (if applicable)

MONTH / DAY / YEAR

MILEAGE : DAY / YEAR

MILEAGE : DAY / YEAR

Comments


Check Battery Condition

GOOD RECHARGE BAD Comments

Check Brakes Measure Front / Rear Break Linings

RF

RR



LF

LR

Over 5mm???

3 - 5mm or 4/32" - 7/32"

Less than 3mm or 4/32"

Measurements Not Taken This Service Visit

Comments Needs Brake Rotors and Pads in future


Check Tires

LF

- ☒ 7/32" or greater
- ☐ 4/32" - 6/32"
- ☐ 3/32" or less

RF

- ☒ 7/32" or greater
- ☐ 4/32" - 6/32"
- ☐ 3/32" or less



- ☒ 7/32" or greater
- ☐ 4/32" - 6/32"
- ☐ 3/32" or less

LR

- ☒ 7/32" or greater
- ☐ 4/32" - 6/32"
- ☐ 3/32" or less

RR

- ☒ LF
- ☒ LR

Wear pattern / Damage
Tire Wear Indications

- ☒ LF
- ☒ LR

- ☐ Alignment Check Recommended
- ☐ Wheel Rotation Recommended

Comments

This Inspection Completed By Your Meister Werks Service Team

Jasmin MC RAE

SERVICE ADVISOR

Michael

TECHNICIAN

CUSTOMER SIGNATURE

Tire Pressure Set to:

Factory Recommendations

PSI

36

FRONT

44

REAR

Exterior

- ☐ Windshield free of cracks *small*
- ☒ Body panel colors match
- ☒ Paint Depth Gauge consistency
- ☐ Rust in seams
- ☒ Seams where the trunk and hood close are properly aligned
- ☒ Seams where doors and fenders meet are properly aligned
- ☒ Weather stripping in good shape
- ☐ Free of body scratches and chips *Some*
- ☒ Free of body dents or panel "waviness"
- ☐ Rims scuffed or dented
- ☐ Shallow tire-tread depth or uneven wearing
- ☒ Spare tire, jack and lugnut wrench present and functional

Engine

- ☒ Free of fluid or oil leaks
- ☐ Oil filler neck not coated with gummy, black deposits
- ☒ Battery terminals free of corrosion
- ☒ Oil dip stick free of dark, black oil
- ☒ Free of odors while engine is running
- ☒ Exhaust pipe emissions are neither blue (indicates engine burns oil) or black

Interior

- ☒ Seats unworn and free of cracks
- ☒ Trunk opens and closes smoothly
- ☒ Doors open and close smoothly
- ☐ Heavy scent of air freshener (may indicate something is being concealed)
- ☒ All gauges, button, and knobs work
- ☒ No dashboard warning lights remain illuminated
- ☒ Stereo works
- ☒ Heater works
- ☒ Air conditioner functional
- ☒ Windshield wipers work
- ☒ Windshield wiper fluid dispenses properly
- ☒ All seats equipped with functional seat belts
- ☒ All seats adjust properly
- ☒ Power windows operate properly
- ☒ Trunk and driver-side door lock and unlock with key
- ☒ Hazard lights function properly
- ☒ Dashboard free of cracks or touch up paint
- ☒ Headliner intact and sun visor functional

Brakes & Steering

- ☒ Car steers straight and does not pull when brakes applied
- ☒ Brakes do not feel "squishy"
- ☒ Emergency brake functional
- ☒ Steering wheel does not vibrate while driving
- ☒ No clicking noises while turning

Other

- ☒ Service and repair records available
- ☒ Owner has legal ownership (Title)
- ☒ Car manual
- ☒ Manual for upgraded radio/equipment etc

Notes

Engine has Minor Coolant Leak on Passenger side Hose Flange
 Has Squeaky Clutch Pedal Assembly
 Exhaust Needs to Reset Clamps/Fasteners
 Has Dull outer Headlight Plastic
 Minor Paint Chip on Hood and Front Bumper
 Brake Rotors are Worn/Drilled Pads 5mm