



For a free account and more info on this vehicle, go to www.MyCarFax.com

First Time Vehicle

CarFax Service History Report

2004 Porsche 911 Carrera - WP0AA29974S622295

Date 5/11/15 Milage 55,112 mi Service Vehicle serviced
Date 1/10/14 Milage 46,469 mi Service Vehicle serviced, Drivability/performance checked, Four wheel alignment performed, Oil and filter changed, Tire condition and pressure checked
Date 1/9/12 Milage 34,573 mi Service Vehicle serviced, Pre-delivery inspection completed, Maintenance inspection completed, Clutch checked, Four wheel alignment performed, Oil and filter changed, Wipers/washers checked
Date 11/9/11 Milage 32,855 mi Service Vehicle serviced, Window tint installed
Date 10/19/11 Milage 32,475 mi Service Vehicle serviced, Pre-delivery inspection completed, Maintenance inspection completed, Four wheel alignment performed, Interior trim checked, Oil and filter changed, Tire condition and pressure checked, Vehicle washed/detailed
Date 7/20/11 Milage 32,093 mi Service Vehicle serviced, Recommended maintenance performed, Oil and filter changed
Date 7/22/09 Milage 29,370 mi Service Vehicle serviced, 30,000 mile service performed, Engine oil/fluid leak checked, Four wheel alignment performed
Date 5/7/08 Milage 24,204 mi Service Vehicle serviced, Recommended maintenance performed, Body electrical system checked, Drivability/performance checked, Engine checked
Date 1/9/08 Milage 22,662 mi Service Vehicle serviced, Interior lights checked
Date 11/26/07 Milage 22,115 mi Service Vehicle serviced, Steering/suspension checked
Date 11/13/07 Milage 21,918 mi

Service Vehicle serviced, Battery/charging system checked
Date 5/22/07
Milage 18,483 mi
Service Vehicle serviced, 15,000 mile service performed, Exterior trim checked, Transmission checked
Date 8/22/06
Milage 13,963 mi
Service Vehicle serviced, Tire condition and pressure checked
Date 6/27/06
Milage 13,099 mi
Service Vehicle serviced, Recommended maintenance performed, Vehicle washed/detailed
Date 6/30/05
Milage 8,566 mi
Service Vehicle serviced, Recommended maintenance performed, Engine checked, Four tires balanced, Four wheel alignment performed, Interior trim checked, Tire(s) balanced