

MULTI-POINT INSPECTION REPORT

Reset



Luke Calabrese

CUSTOMER NAME

ZQW562 (WA)

HO / TAG

MILEAGE

1977 Porsche 911 S

YEAR / MODEL

9117200204

VIN

2.7L H6 Gas FI

ENGINE SIZE

09.28.2026

DATE

Checked and Okay at this time

May Require Future Attention

Requires Immediate Attention

Check Fluid Levels and Fill

OK FILL

OK FILL

- | | |
|--|--|
| ☒ ☐ Engine Oil | ☒ ☐ Brake Reservoir |
| ☐ ☐ Windshield Washing | ☒ ☐ Headlamp Washer |
| ☐ ☐ Power Steering | ☐ ☐ Coolant Recovery Reservoir |
| ☐ ☐ Transmission (if equipped w/ dipstick) | |

Check Following Systems / Components

- | |
|---|
| ☒ ☐ Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps |
| ☒ ☐ Visually inspect headlamp alignment |
| ☒ ☐ Windshield washer spray, wiper operation and wiper blades |
| ☒ ☐ Windshield cracks and/or chips |
| ☒ ☐ Heating, ventilation and air conditioning check |
| ☒ ☐ Engine air cleaner filter |
| ☒ ☐ Oil and/or fluid leaks |
| ☒ ☐ Contant velocity (CVI drive axle boots if equipped) |
| ☒ ☐ Exhaust system (leaks, damage, loos parts) |
| ☒ ☐ Steering and steering linkages |
| ☒ ☐ Stocks/struts, air suspenscion and other suspension components for leaks and/or damage |
| ☒ ☐ Brake systems (including lines, hoses and parking brake) |
| ☒ ☐ Engine cooling system, hoses and clamps |
| ☒ ☐ Radiator, heater and air conditioning hoses for leaks / damage |
| ☒ ☐ Accessory drive belts |
| ☒ ☐ Clutch operation (if equipped) |
| ☒ ☐ State inspection due (if applicable) |

MONTH / DAY / YEAR

☒ ☐ Your last completed maintenance

MILEAGE : DAY / YEAR

☒ ☐ Your next factory scheduled maintenance is due at

MILEAGE : DAY / YEAR

Comments

Engine and Transmission leaking from multiple locations.

This Inspection Completed By Your Meister Werks Service Team

Dave

SERVICE ADVISOR

Mischa

TECHNICIAN

CUSTOMER SIGNATURE


Check Battery Condition

☒ GOOD ☐ RECHARGE ☐ BAD Comments

Check Brakes Measure Front / Rear Break Linings

RF ☒ ☐ ☐

RR ☒ ☐ ☐



LF ☒ ☐ ☐

LR ☒ ☐ ☐

Over 5mm????

3 - 5mm or 4/32" - 7/32"

Less than 3mm or 4/32"

Measurements Not Taken This Service Visit

Comments


Check Tires

LF

- | |
|--|
| ☒ 7/32" or greater |
| ☐ 4/32" - 6/32" |
| ☐ 3/32" or less |

RF

- | |
|--|
| 7/32" or greater ☒ |
| 4/32" - 6/32" ☐ |
| 3/32" or less ☐ |



- | |
|--|
| ☒ 7/32" or greater |
| ☐ 4/32" - 6/32" |
| ☐ 3/32" or less |

LR

- | |
|--|
| 7/32" or greater ☒ |
| 4/32" - 6/32" ☐ |
| 3/32" or less ☐ |

RR

☒ ☐ ☐ LF

Wear pattern / Damage

LF ☒ ☐ ☐

☒ ☐ ☐ LR

Tire Wear Indications

LR ☒ ☐ ☐

☐ Alignment Check Recommended

☐ Wheel Rotation Recommended

Comments

New tires.
Missing wheel center caps

Tire Pressure Set to:

Factory Recommendations

PSI

29

FRONT

34

REAR

Exterior

- Windshield free of cracks
- ☐ Body panel colors match
- ☐ Paint Depth Gauge consistency
- ☐ Rust in seams
- Seams where the trunk and hood close are properly aligned
- Seams where doors and fenders meet are properly aligned
- Weather stripping in good shape
- Free of body scratches and chips
- ☐ Free of body dents or panel "waviness"
- ☐ Rims scuffed or dented
- ☐ Shallow tire-tread depth or uneven wearing
- Spare tire, jack and lugnut wrench present and functional

Engine

- ☐ Free of fluid or oil leaks
- Oil filler neck not coated with gummy, black deposits
- Battery terminals free of corrosion
- Oil dip stick free of dark, black oil
- Free of odors while engine is running
- Exhaust pipe emissions are neither blue (indicates engine burns oil) or black

Interior

- Seats unworn and free of cracks
- Trunk opens and closes smoothly
- ☐ Doors open and close smoothly
- Heavy scent of air freshener (may indicate something is being concealed)
- All gauges, button, and knobs work
- No dashboard warning lights remain illuminated
- Stereo works
- Heater works
- ☐ Air conditioner functional
- Windshield wipers work
- Windshield wiper fluid dispenses properly
- All seats equipped with functional seat belts
- All seats adjust properly
- Power windows operate properly
- Trunk and driver-side door lock and unlock with key
- Hazard lights function properly
- Dashboard free of cracks or touch up paint
- ☐ Headliner intact and sun visor functional

Brakes & Steering

- Car steers straight and does not pull when brakes applied
- Brakes do not feel "squishy"
- Emergency brake functional
- Steering wheel does not vibrate while driving
- No clicking noises while turning

Other

- ☐ Service and repair records available
- ☐ Owner has legal ownership (Title)
- ☐ Car manual
- ☐ Manual for upgraded radio/equipment etc

Notes

- Multiple engine oil leaks.
- Multiple transmission is leaking gear oil.
- Metallic Paint is resprayed - Metallic flecks are not uniform
- Orange peel in paint
- New upholstery - Foam under upholstery was not replaced. Can tell that cushions are uneven.
- Headliner next to sunroof is coming out of trim.
- Stick shifter is not attached properly and difficult to get into gear. Needs adjusted.
- Dent in right rear bumper accordion forward.
- Rocker trim missing, exposed holes in body on both sides.
- Doors do not lock or open from the inside (unsafe)
 - * Found out when seller picked up that you have to pull the straps to open the doors.
 - * Seller did not tell us this.
- Wheel center caps are missing.
- Engine starts and runs good.
- Clutch and transmission feel solid.